



Measure down from top of flange 4 1/2" and from the radius aft 3 1/2", this is the center of where you would need to drill a 4 1/2" hole for the inspection plate.